



**Auto Timing Belt Tensioner Pulley
VKM81004**

XYB BEARINGS® is one of the famous China Auto Timing Belt Tensioner Pulley VKM81004 manufacturers and Automobile timing belt tensioner pulley suppliers. **Automobile timing belt tensioner pulley used for TOYOTA Camry Part Number VKM81004, 13503-63020, 13503-88360 [XTN6007]**

Product Description

Vehicle	OEM NO.
TOYOTA	13503-63010
TOYOTA	13503-63011
TOYOTA	13503-63020
TOYOTA	13503-63021
TOYOTA	13503-70040
TOYOTA	13503-88360
TOYOTA	13503-88361
TOYOTA	13503-88380
TOYOTA	13503-88560
SKF	VKM81004
DAYCO	ATB2107
GATES	T42025
INA	532 0091 20
OPTIMAL	0-N991
QUINTON HAZELL	QTT459

XYB BEARINGS® is an professional Auto Timing Belt Tensioner Pulley VKM81004 for TOYOTA Camry Part Number 13503-63020, 13503-88360 [XTN6007] manufacturer, factory and supplier in China. We have been specialized in auto parts for many years. Our products have a good price advantage and cover most of the European and American markets. We look forward to becoming your long-term partner in China.

XYB Automobile Tensioner Pulley [XTN6007] Parameter

Outer Diameter [mm]: 58

Width [mm]: 29

Weight [kg]: 0.26

Tensioner Pulley Actuation: Manual

Automobile timing belt tensioner pulley used for TOYOTA Camry Part Number VKM81004, 13503-63020, 13503-3011 [XTN6007]



Application

VEHICLE	Model	Engine	Power	Year
TOYOTA	TOYOTA RAV 4 I (SXA1_)			1994/01-2000/09
TOYOTA	TOYOTA CRESSIDA Saloon (_X6_)			1980/09-1992/09
TOYOTA	TOYOTA CAMRY (_CV1_, _XV1_, _V1_)			1991/06-1997/09
TOYOTA	TOYOTA CAMRY Saloon (_V1_)			1983/02-1988/07
TOYOTA	TOYOTA CAMRY (_V2_)			1986/10-1993/02
TOYOTA	TOYOTA CAMRY Liftback (_V1_)			1983/01-1988/01
TOYOTA	TOYOTA CAMRY Station Wagon (_XV1_, _CV1_, _V10)			1991/06-1997/08
TOYOTA	TOYOTA CAMRY Station Wagon (_V2_)			1986/11-1991/06

TOYOTA	TOYOTA CARINA II Saloon (_T15_)	1983/0/-1988/05
TOYOTA	TOYOTA CARINA E Saloon (_T19_)	1992/04-1997/09
TOYOTA	TOYOTA CARINA E (_T19_)	1992/04-1997/09
TOYOTA	TOYOTA CARINA E Sportswagon (_T19_)	1992/02-1997/09
TOYOTA	TOYOTA CARINA II Saloon (_T17_)	1987/12-1992/06
TOYOTA	TOYOTA CARINA II (_T17_)	1987/12-1992/06
TOYOTA	TOYOTA CARINA II Station Wagon (_T17_)	1987/12-1992/04
TOYOTA	TOYOTA CARINA II (_T15_)	1983/10-1988/05
TOYOTA	TOYOTA CELICA Hatchback (ST16_, AT16_)	1985/08-1989/12
TOYOTA	TOYOTA CELICA Coupe (AT18_, ST18_)	1989/09-1993/11
TOYOTA	TOYOTA CELICA (ST20_, AT20_)	1993/11-1999/11
TOYOTA	TOYOTA CELICA Convertible (ST16_, AT16_)	1985/08/1989/08
TOYOTA	TOYOTA CELICA Convertible (AT18_, ST18_)	1989/10-1993/11
TOYOTA	TOYOTA CELICA Coupe (ST16_, AT16_)	1985/09-1989/08
TOYOTA	TOYOTA PICNIC (_XM10)	1996/05-2001/12
TOYOTA	TOYOTA CELICA (AT16_, ST16_)	1985/08-1989/08
TOYOTA	TOYOTA CELICA Convertible (AT20_, ST20_)	1993/11-1999/08
TOYOTA	TOYOTA AVENSIS (_T22_)	1997/09-2003/02
TOYOTA	TOYOTA AVENSIS Station Wagon (_T22_)	1997/09-2003/02
TOYOTA	TOYOTA CAMRY (_CV2_, _XV2_)	1996/08-2001/11
TOYOTA	TOYOTA AVENSIS Liftback (_T22_)	1997/09-2003/02
TOYOTA	TOYOTA RAV 4 I Cabrio (SXA1_)	1997/12-2000/06
TOYOTA	TOYOTA MR 2 II (SW2_)	1989/12-2000/05

Features:

- a) Tensioner pulley bearing is single row radial ball bearing.
- b) Heat stabilized rings, special grease, a seal and retainer.

- c) High precision technology and material to long-time life.
- d) To provide belt with tension while transferring drive force from crankshaft, preventing belt slippage.
- e) More than 300 hours life test on the test bench for tensioner of passenger vehicles.
- f) More than 600 hours life test on the test bench for tensioner of commercial vehicles.
- g) Our tensioner pulley and tensioner bearings begin with the XTN prefix.